

# Installation Instructions

## Surface Fixed


Petal Drum  
Page 1 of 3




### Instrument Components:

-  x4  
M6x20 Security Screw
-  x2  
M6 Saddle Strap

Metric Conversion:  
1080mm/ 42.5"  
1.5m/ 59"



(1.3)



(1.2)

Weight of heaviest part 7.5kg

1. Instrument will arrive on site fully assembled. (1.1)  
(See Assembly Guide)



2. Attach Surface Fixing posts to legs. (1.2) (See Surface Fix Post Installation Sheet)

3. Locate Plate in desired location and mark holes to fix to desired surface.

4. Fix to Surface using recommended ground anchors not supplied

5. Make sure all fixings are covered and secure using cover caps provided.


6. Attach the 1 of the beaters to each of the saddle strap on the hex frame. (1.3)



Pair Small Red Beaters X1

Surface Fix Components:

 x1  
M10x70 Security Screw


 x1  
M10 Barrel Nut



Spares available from  
[percussionplay.com](http://percussionplay.com) or from your  
local distributor

17 Kg

## Tools:




Install 3X PU Inserts into each arm before installing petal section



## COMPONENTS LIST:

- 2 Part Cover Cap X8
- M8X30 Pin torx X3
- Saddle Strap X2
- M6x20 Pin torx X6
- M10x70 Pin torx X1
- M10 Barrel Nut Pin torx X1
- Petal Drum Frame Insert X3



Thread Lock Solution  
Required (Not Supplied)

## Surface Fixed Petal Drum Page 2 of 3



## Instrument Components:

x4  
M6x20 Security Screw

x2  
M6 Saddle Strap

Thread Lock Solution  
Required (Not Supplied)



Pair Small Black  
Beaters X1

## Surface Fix Components:

x1  
M10x70 Security Screw

x1  
M10 Barrel Nut



Spares available from  
[percussionplay.com](http://percussionplay.com) or from your  
local distributor

17 Kg

## Surface Fixed Petal Drum Page 3 of 3



### Components:



x1


M10 Barrel Nut




x1

M10x70 Security Screw


Thread Lock Solution  
Required (Not Supplied)



Locate the Surface fix Plate into the leg of the instrument.



Fix instrument to Surface fix plate using M10 bolt and Barrel Nut and use **thread locking solution** to prevent fixings working loose.



Fix Surface Plate to the ground surface **Ground Anchors Not provided** cover fixings with caps provided

