


Installation Instructions

Surface Fixed

Sansa Rimba
Page 1 of 3




Instrument Components:

-  x4
M8 Nyloc Nut
-  x2
M6x20 Security Screw
-  x4
2 Part Cover Cap
-  x1
M6 Saddle Strap

Metric Conversion:

250mm	/	10"
300mm	/	12"
450mm	/	18"
700mm	/	28"
850mm	/	33"
1.5m	/	59"



Weight of heaviest part 10.5kg (Sansa Rimba)

1. Attach the steel legs to the base of the instrument with the M8 Nyloc Nuts and 2 part security caps. (1.1) (See Assembly Guide)





2. Attach Surface Fixing posts to legs (1.2) (See Ground Fix Post Installation Sheet)

3. Locate Plate in desired location and mark holes to fix to desired surface.

4. Fix to Surface using recommended ground anchors not supplied

5. Make sure all fixings are covered and secure using cover caps provided

6. Attach the 1 pair of beater to the saddle strap on the leg. (1.3)




Ground Anchors not supplied

Spares available from percussionplay.com or from your local distributor

14 Kg

Tools:



 x1
 x1

TX 30 Driver Bit TX 40 Driver Bit


Surface Fixed
Sansa Rimba
Page 2 of 3




- Instrument Components:**
-  x4
M8 Nyloc Nut
 -  x2
M6x20 Security Screw
 -  x4
2 Part Cover Cap
 -  x1
M6 Saddle Strap



Thread Lock Solution
Required (Not Supplied)




PPSANS FRONT




PPSANS SIDE

COMPONENTS LIST:

-  2 Part Cover Cap X8
-  M8 Nyloc nut X4
-  M10 Nut X4
-  M10x200 Threaded Bar X2
-  Saddle Strap X1
-  M6x20 Pin torx X2
-  M10x70 Pin torx X1
-  M10 Barrel Nut Pin torx X1





Thread Lock Solution
Required (Not Supplied)

Pair Small Red Beaters X1

Surface Fix Components:

-  x1
-  x1
-  x4

Ground Anchors
not supplied

Spares available from
percussionplay.com or from your
local distributor

19.5Kg

Tools:

 x2
TX 45 Driver Bit

Surface Fixed

Sansa Rimba
Page 3 of 3



Components:



x1

M10 Barrel Nut



x1

M10x70 Security Screw




x4

2 Part Cover Cap

Thread Lock Solution
Required (Not Supplied)


Metric
Conversion:
50mm/ 2"
250mm/ 10"
350mm/ 14"
400mm/ 16"
450mm/ 18"

1




Locate the Surface fix
Plate into the leg of the
instrument.

2



Fix instrument to Surface
fix plate using M10 bolt
and Barrel Nut and use
thread locking solution
to prevent fixings working
loose.

3



Fix Surface Plate to the
ground surface **Ground
Anchors Not provided**
cover fixings with caps
provided

Repeat Parts 1-3 for both legs



MADE IN
BRITAIN
BSEN 1176